

Seat No.: _____

Enrolment No. _____

GUJARAT TECHNOLOGICAL UNIVERSITY

BE - SEMESTER-IV(NEW) – EXAMINATION – SUMMER 2019

Subject Code:2142503

Date:09/05/2019

Subject Name: Metrology and Measurement

Time:02:30 PM TO 05:00 PM

Total Marks: 70

Instructions:

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.

		MARKS
Q.1	(a) Draw and explain generalized measurement system.	03
	(b) Compare the terms: Accuracy and Precision.	04
	(c) Define Metrology. Explain mechanical strain gauges.	07
Q.2	(a) Explain the calibration process of temperature measuring devices.	03
	(b) Describe the working principle of Photoelectric tachometer.	04
	(c) Explain the working principle of LVDT with merits and demerits.	07
OR		
	(c) List out various temperature measuring devices. Explain working of thermo couples briefly.	07
Q.3	(a) Classify various linear measuring instruments.	03
	(b) Draw a neat sketch of Vernier Height Gauge.	04
	(c) Write a short note on Vernier Micrometer.	07
OR		
Q.3	(a) Enlist various errors arise during the manufacturing of screw threads.	03
	(b) Write a short note on light interference microscope.	04
	(c) Explain the working principle of sine bar with example.	07
Q.4	(a) Classify various angular measuring instruments.	03
	(b) Write a short note on tool maker's microscope.	04
	(c) Explain gear tooth terminology with neat sketch.	07
OR		
Q.4	(a) Enlist various surface measuring instruments.	03
	(b) What is the application of angle dekkor?	04
	(c) Explain the working of Taylor Hobson Talysurf with neat sketch.	07
Q.5	(a) What do you mean by pyrometry? Enlist various types of pyrometers.	03
	(b) What are the merits and demerits of mechanical comparator?	04
	(c) Explain the measurement of effective diameter by Two wire method.	07
OR		
Q.5	(a) Explain the function of Slip Gauges. Explain Wringing method in detail.	03
	(b) What are the merits and demerits of pneumatic comparator?	04
	(c) Draw and explain working of Co-ordinate Measuring Machine.	07
