

GUJARAT TECHNOLOGICAL UNIVERSITY**BE - SEMESTER– VIII (NEW) EXAMINATION – WINTER 2021****Subject Code:2180207****Date:23/11/2021****Subject Name:Applied Industrial Engineering in Automobile****Time:10:30 AM TO 01:00 PM****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. Simple and non-programmable scientific calculators are allowed.

		MARKS
Q.1	(a) Define Production, Planning and Control.	03
	(b) Differentiate between Method Study & Work Measurement.	04
	(c) What are the drivers of Quality and explain it?	07
Q.2	(a) Describe Operation Process Chart with suitable example.	03
	(b) Define Productivity. Discuss factors affecting productivity.	04
	(c) What is Therbligs? Explain therbligs in technical aspects with their symbols.	07
OR		
	(c) What is SWOT Analysis and why is it required?	07
Q.3	(a) Define Quality in terms of three Quality Gurus.	03
	(b) Explain four different types of Customers.	04
	(c) Explain 5'S Techniques with reference to quality.	07
OR		
Q.3	(a) Discuss the benefits of Quality Management.	03
	(b) Discuss principle of Deming for Total Quality Management.	04
	(c) Illustrate "Ishikawa Diagram" in context to automobile industries.	07
Q.4	(a) State benefits of implementing ISO 14000 in an organization.	03
	(b) Describe Vision and Mission statements of an organization.	04
	(c) Write short note of ISO: 9000.	07
OR		
Q.4	(a) Explain the concept of 6 σ in brief and its importance.	03
	(b) Explain following terms: (1) Bathtub Curve, (2) MTTF, (3) MTBF, (4) MTTR.	04
	(c) Describe the Failure Mode and Effect Analysis (FMEA) with suitable example along with its advantages.	07
Q.5	(a) Define: (1) PERT (2) CPM (3) Linear Programming.	03
	(b) Describe concept of Just in Time for manufacturing.	04
	(c) Explain North West Corner Method with suitable example.	07
OR		
Q.5	(a) Explain Economic Order Quantity (EOQ) models.	03
	(b) What are the limitations of Operation Research?	04
	(c) Explain Least Count Method with suitable example.	07
